

1 Update verfügbar

Gerätesoftware

Installieren

Version: 5.70

Dateigröße: 72,97 MB

Installationszeit: 1 Minute

- Fixed an issue where the Bluetooth would make incorrect tone through headset.
- Fixed an issue where navigation instructions interrupt music streaming.
- Fixed an issue where invalid language files would cause unit to reboot at power up.
- Fixed issues where the routing algorithm creates routes that go off a big road and then back on to a big road after 200 meters.
- Fixed an issue where users were not able to interact with the safety mode message via MMC.
- Fixed an issue where the QR code for downloading the Smartphone Link app would lead to an invalid link.